

44 Parker Hill Rd. Ext.

STATE OF CONNECTICUT

CONNECTICUT HISTORICAL COMMISSION

59 South Prospect Street, Hartford, Connecticut 06106
(203) 566-3005

HISTORIC RESOURCES INVENTORY FORM
For Buildings and Structures

FOR OFFICE USE ONLY			
TOWN NO.:	SITE NO.:		
UTM: 18/			
QUAD:			
DISTRICT:	R	NR:	ACTUAL POTENTIAL

IDENTIFICATION

- 1. BUILDING NAME: Common: _____ Historic: _____
- 2. TOWN/CITY: Killingworth VILLAGE COUNTY: Middlesex
- 3. STREET & NUMBER (and/or location): Parker Hill Road
- 4. OWNER(S): James Bliedung - John Beal PUBLIC PRIVATE
- 5. USE: Present: Residential Historic: _____
- 6. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: yes no
Interior accessible: yes, explain _____ no

DESCRIPTION

- 7. STYLE OF BUILDING: Cape Cod Cottage DATE OF CONSTRUCTION: Early 1800's
or late 1700's
Estimated
- 8. MATERIAL(S) (indicate use or location when appropriate):

<input checked="" type="checkbox"/> clapboard	<input type="checkbox"/> asbestos siding	<input type="checkbox"/> brick
<input type="checkbox"/> wood shingle	<input type="checkbox"/> asphalt siding	<input type="checkbox"/> fieldstone
<input type="checkbox"/> board & batten	<input type="checkbox"/> stucco	<input type="checkbox"/> cobblestone
<input type="checkbox"/> aluminum siding	<input type="checkbox"/> concrete: type: _____	<input type="checkbox"/> cut stone: type: _____
<input type="checkbox"/> other: _____		
- 9. STRUCTURAL SYSTEM:
 wood frame post and beam balloon
 load bearing masonry structural iron or steel
 other: Plank walls
- 10. ROOF: type:
 gable flat mansard monitor sawtooth
 gambrel shed hip round other _____
material:
 wood shingle roll asphalt fln slate
 asphalt shingle built up tile other: _____
- 11. NUMBER OF STORIES: 1 and attic APPROXIMATE DIMENSIONS: 24' x 20' + addition
- 12. CONDITION: Structural: excellent good fair deteriorated
Exterior: excellent good fair deteriorated
- 13. INTEGRITY: Location: on original site moved, when: _____
Alterations: no yes, explain: Addition (see other side)
- 14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES:
 barn shed garage other landscape features or buildings: _____
 carriage house shop garden
- 15. SURROUNDING ENVIRONMENT:
 open land woodland residential scattered buildings visible from site
 commercial industrial rural high building density
- 16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
Lovely setting on 13 acres on country road. Nice stream and pond.

17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior):

3/4 Cape. Windows replaced with 2/2 oversized. Interior plaster walls removed to show old plank walls, which present owner did not understand that these walls were not paneling but part of construction.

Original house had 3 rooms and loft. 1950's large addition. Nice old fireplaces.


SIGNIFICANCE

Architect: _____ Builder: _____

18. HISTORICAL OR ARCHITECTURAL IMPORTANCE:

PHOTOGRAPH

photographer: Walter B. Dunden, Jr.
date: Aug. 1978 view: Front
negative on file: CRERPA film 6 5-50



COMPILED BY:

name: Clarissa Dundon date: Aug. 1978
organization: Killingworth Historical Society
address: Killingworth

19. SOURCES:

1874 Burr's Map - H. Burr
More research is needed on this section of town

20. SUBSEQUENT FIELD EVALUATIONS:

21. THREATS TO BUILDING OR SITE:

none known highways vandalism developers other: _____
 renewal private deterioration zoning explanation: _____

